





# Montageanleitung Mounting Instruction Instructions de montage Istruzioni di montaggio










**1**





**2**









3







4







5




6




7a



| S   | X         |
|-----|-----------|
| 550 | 193,5 - M |
| 555 | 188,5 - M |
| 560 | 183,5 - M |
| 565 | 178,5 - M |
| 570 | 178,5 - M |
| 575 | 178,5 - M |
| 580 | 178,5 - M |





| S   | B = C       |
|-----|-------------|
| 550 | 346 - M - Z |
| 555 | 341 - M - Z |
| 560 | 336 - M - Z |
| 565 | 331 - M - Z |
| 570 | 326 - M - Z |
| 575 | 321 - M - Z |
| 580 | 316 - M - Z |






| S   | B = C           |
|-----|-----------------|
| 550 | 348 - F - M - W |
| 555 | 343 - F - M - W |
| 560 | 338 - F - M - W |
| 565 | 333 - F - M - W |
| 570 | 328 - F - M - W |
| 575 | 323 - F - M - W |
| 580 | 318 - F - M - W |






8a







| S   |        |   |
|-----|--------|---|
| 550 |        | ✓ |
| 555 |        | ✓ |
| 560 |        | ✓ |
| 565 |        | ✓ |
| 570 | X = 5  | ✓ |
| 575 | X = 10 | ✓ |
| 580 | X = 15 | ✓ |




9a




7b



| S   | X         |
|-----|-----------|
| 550 | 193,5 - M |
| 555 | 188,5 - M |
| 560 | 183,5 - M |
| 565 | 178,5 - M |
| 570 | 178,5 - M |
| 575 | 178,5 - M |
| 580 | 178,5 - M |





| S   | B = C       |
|-----|-------------|
| 550 | 346 - M - Z |
| 555 | 341 - M - Z |
| 560 | 336 - M - Z |
| 565 | 331 - M - Z |
| 570 | 326 - M - Z |
| 575 | 321 - M - Z |
| 580 | 316 - M - Z |






| S   | B = C           |
|-----|-----------------|
| 550 | 348 - F - M - W |
| 555 | 343 - F - M - W |
| 560 | 338 - F - M - W |
| 565 | 333 - F - M - W |
| 570 | 328 - F - M - W |
| 575 | 323 - F - M - W |
| 580 | 318 - F - M - W |





8b













| S         |  |
|-----------|--|
| 550       |  |
| 555       |  |
| 560       |  |
| 565       |  |
| 570 X = 2 |  |
| 575 X = 4 |  |
| 580 X = 6 |  |




9b





10







11





12





min. 2x  
3,5 x .....



3,5 x .....

